



GAI Aircraft Services LLC.

7940 Airpark Rd. Hangar M
Gaithersburg, MD 20879

Phone # 2404776617

Invoice

Date	Invoice #
7/11/2016	1671

Bill To

Service	Service Date	Tach	N Number
Annual	7/11/2016	334.1	593MS

Quantity	Item Code	Description	Price Each	Amount
39	Annual Inspection	Annual Inspection	85.00	3,315.00
3	Hour Labor	Replaced both vacuum filters, instrument filter, induction air filters three 40S5-8 Cam Lock fasteners and tie wrap of the right propeller's de-ice boot.	85.00	255.00
16	Hour Labor	Stripped, etched, alodined, primed both engine nacelles and wings to the inboard sides. No charge for paint	85.00	1,360.00
1.5	Hour Labor	Repaired right wing Nav and strobe light wiring.	85.00	127.50
2	Hour Labor	RH Replaced the #s 1, 2 & 5 cylinder push rod tube seals.	85.00	170.00
2	Hour Labor	Tightened the governor's base nuts. Tightened the fuel pump mounting bolts to stop a fuel leak. Replaced the #s 2, 4 & 6 valve cover gaskets	85.00	170.00
4	Hour Labor	LH Replaced eleven sets of push rod tube seals and ten of the valve cover gaskets.	85.00	340.00
0.5	Hour Labor	LH L mag P laed replaced	85.00	42.50
4	Hour Labor	Preformed 500 hr inspection on both L engine magneto . Replaced both contact assemblys . installed mag and timed to the engine	85.00	340.00
16	20W50	Phillips Oil	6.70	107.20T
2	48108-1	Champion Oil Filter	29.00	58.00T
13	Spark plug RHM3...	Spark plug RHM38E	42.00	546.00T
2	Vacuum Filter RA...	vacuum Filter	26.00	52.00T
1	Air filter BA105		55.04	55.04T
1	Instrument filter		38.00	38.00T
1	Cable	Stabilizer cable p/n MC62701-013	100.00	100.00T
13	Valve cover seal	Valve cover seal 655704	5.00	65.00T
14	push rod	push rod O-ring 630286	5.00	70.00T
14	push rod	Push rod seal 641607	5.00	70.00T
1	paint materials		250.00	250.00T
1	Miscellaneous Ma...	Miscellaneous Materials	25.00	25.00T
		Sales Tax	6.00%	86.17

Thank you for your business.

Total \$7,642.41